

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
PER-59635 Site Access Permit	Decmil Southern Pty Ltd	Ison Rd Overpass 35.000 KP - 37.000 KP / SAP_0982-O TPA0030723 Permit to Foul: 35.000kp – 37.000kp on the EAST Line Absolute occupation: Signal Post 18 at Werribee to Signal Post MNJ 18 on the WEST Line Work Type Access approved to undertake the following works Surveying Site Inspection Access Tracks Rectification Works Handrail Installation Concrete Patching works Painting of Bridge Elements Swale Excavation QA Testing Anti Throw Screen Defect Repairs Safe Working SAP is invalid without the corresponding SWO Circular.	Andrew Nguyen	12:01 AM 12/01/2026	11:57 PM 7/02/2026	In Progress